MOPA S	Entricks Her rowskie	C. ASSIT	IED MESSAGE	3"CIIS A 23"MA MA" :		MFG. 3-32 ROUTING
	Approved For Release	The second secon	THE PERSON NAMED IN POST OF THE PERSON ASSESSMENT OF THE PERSON AS	00000018	and the second statement of the second	
DATE		S E C		2		The state of the s
	0008Z 08 APR 64	DE U	N & &	3		11
				4	Andre Greeklighte der allegen gehalte die der eine	12
AND THE PROPERTY OF THE PROPER		giginar maganingkigkig kali sareh aresa yi. segimininar minari dibakindi olah dibakindi dibakindi dibakindi di segimenyan mendisyada dibakingan digisir yingkigasiginin Japanindir Daula mijida dibakin gida dibakinya terjah	ong pantan manamandar banggan jagan nghyapan nghyapan na manggan gang pantan dan gang dan sa sa sa sa sa sa sa Di pendah sananik dan menggan banggan panban dan menggan pantan sa	5 6		14
TO	:DIRECTOR			7	AND THE PROPERTY OF THE PROPER	15
FRON			f.	8		16
ACTIO	N: 0PS 1-8		ROUTINE			
INFO	4					
	TOR 9444Z 98 APR 64			1 1		IN 7221
		25 1 1	* * * * * * * * * * * * * * * * * * * *			
	25X1A	25X1A	A Control of the Cont	ingly again weight of many parties of the state of the st		
то		INFO			CITE	
P			*.	7 °	_	25X1A
		•		•		25/17
	A. S154A	25X1A		**		
4						
;	-					
	C. HTA-3B/D-19/2°/	78 DEGREES	•			
i	D. 2.99 2.92/2.91	2.61	•	t.		
						4
•	E. 8492/232-28-7-3	(9L) 327-2	7-7-3 (9R)			
	F. (1) GOOD					
			• .	٠.		
	(2) GOOD					
	(3) GOOD					
			• 0			
	(4) GOOD					
	(5) GOOD					
			le le			
	(6) GOOD		i			
			,			
1	(7) OPERATING					

G. REMARKS: TAKE RECEIVED AT @7/@14@Z APR IN COVERED, METAL BOXES.

ONE SIDE SEALED; OTHER UNSEALED. PROCESSED TRACKER RECEIVED FROM

S144A IN GOOD CONDITION. SLIGHT CREASE FIRST FEW FRAMES 9L DUE TO

HEAT SEAL SPLICE. DEVELOPER STREAK IN FRAME @G17L. MILD PRESSURE

SECRET

CROW 1
Excluded from automotic downgrosting and declastification

Approved For Release 2002/09/05 : CIA-RDP89B00569R000800180031-4

25X1A								
	(IN	72216)	s	E	C A	T	PAGE	TWO

MARKS FIRST 1000 FRAMES OR. FRAMES DID NOT MATCH AT END OF TAKE.

SR HAD 1721; 9L HAD 1732. NO OVERRUN WAS NOTED ON EITHER SIDE.

MANUFACTURER SPLICES NOTED ON FRAMES 9008R AND L. CONFIGURATION

OPERATED SATISFACTORILY.

END OF MESSAGE